

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
12/04/2017
Submitted Date:
12/06/2017
Document Number:
682502904

FIELD INSPECTION FORM

Loc ID 453292 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 61650
Name of Operator: MURFIN DRILLING COMPANY INC
Address: 250 N WATER ST STE 300
City: WICHITA State: KS Zip: 67202

Findings:
3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		sgunzelman@murfininc.com	
		lrodak@murfininc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453286	WELL	DG	12/06/2017		073-06735	Legacy 11-30	CI

General Comment:
This is a pre-drill construction and stormwater inspection.

Location Construction

Location ID: 453292 CDP: _____
Comment: _____
Corrective Action: _____ Date: _____

Form 2A COAs:
Comment: _____
Corrective Action: _____ Date: _____

Wildlife BMPs:
Comment: _____
Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
DITCHES	Yes		

Comments: Erosion BMPs: Surface owner has a network of terraces/ditches along the slope of the hill. Operator has incorporated the vegetated ditches along the west end of the location into their stormwater BMPs. Stormwater and sediment control BMPs installed prior to construction/excavation operations.
Other BMPs: _____
Corrective Action: _____ Date: _____

SLOPE ROUGHENING	Yes	
------------------	-----	--

Comments: Erosion BMPs: Operator has installed surface roughening along perimeter of the location. In the sites current condition at time of inspection, BMP is satisfactory, however, surface roughening is a temporary BMP that should be used in conjunction with other controls.

Other BMPs:

Corrective Action: _____ Date: _____

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 453286 Type: WELL API Number: 073-06735 Status: DG Insp. Status: CI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682502905	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4319354