

Litton Federal Gas Unit 2 Closure Photos Inspection 685303917



New Well Head Sign in place



Rig Anchors Marked



Tank sign in conspicuous location



Stained soil around well head cleaned up and disposed of at the Operation Center Soil Box for remediation in bulk at IEI in Farmington NM