



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Flat, unused portions of the project area have recently been seeded and straw mulched.**



**Photo 3. View of rock run-down stormwater controls in the northern portion of the project area.**



**Photo 4. View of germination Quadrat Sample-1 in the southwestern portion of the project area, facing center.**



**Photo 5. View of germination Quadrat Sample-2 in the southern portion of the project area, facing center.**



**Photo 6. Closeup view of typical young grass seedlings, appear to be blue grama (*Bouteloua gracilis*) within the germination quadrat sample area.**



**Photo 7. View of germination Quadrat Sample-6 in the northeastern portion of the project area. Blue twine needs to be removed.**



**Photo 8. Closeup view of blue twine section, typical of many scattered around the interim reclamation area.**