

Interim Reclamation and Stormwater Inspection

December 4, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 451533

Weld County, CO

SWSW Section 3 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HAMMER /3-5HZ
Location ID: 451533



Photo 1. Photo taken from the entrance of the location, facing North. Tracking pad device has been installed.



Photo 2. Photo taken from the northeast location, facing West. Ditch and berm BMP installed around the perimeter of the location.

Inspection Photos
Location Name: HAMMER /3-5HZ
Location ID: 451533



Photo 3. Photo taken from the northwest location, facing East. Sediment trap installed with a stabilized outlet.



Photo 4. Photo taken from the northern location, facing East. Appears topsoil has been salvaged and stored along the northern perimeter of the location. North-facing side slope does not appear to be stabilized.

Inspection Photos
Location Name: HAMMER /3-5HZ
Location ID: 451533



Photo 5. Photo taken from the northwest location, facing South. See comments under Photo 2.



Photo 6. Photo taken from the southwest location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: HAMMER /3-5HZ
Location ID: 451533



Photo 7. Photo taken from the southern location, facing East. See comments under Photo 2.



Photo 8. Photo taken from the southeast location, facing North. See comments under Photo 3.

Inspection Photos
Location Name: HAMMER /3-5HZ
Location ID: 451533



Photo 9. Photo taken from the southern location, facing East. See comments under Photo 2. Culverts installed in conjunction with the ditch BMP and road-side ditch along the access road.

Photo 2. Photo taken from the southwest location of the east pad, facing North. Ditch and berm BMP installed around the perimeter of the location.