

Inspection Photos

Location Name: Divide Rd WTF Pipeline Release

Spill/Release Point ID #453066

REM #10691



11/28/2017. First monitoring well installed at the bottom of the valley, north side of the Divide Rd Point of Release (Divide Rd at the top of the ridge).



12/01/2017. Pot holing to uncover 10" condensate pipeline in the pipeline corridor that runs on the north side of the Divide Rd.



Inspection Photos
Location Name: Divide Rd WTF Pipeline Release
Spill/Release Point ID #453066
REM #10691



Looking southeast, from the road to A27 CDP. Divide Rd at the top of the ridge. Installing monitoring wells downhill of the Point of Release (POR)



Looking west. Divide road follows the ridge. To the right (north) pipeline corridor follows the road.

Inspection Photos
Location Name: Divide Rd WTF Pipeline Release
Spill/Release Point ID #453066
REM #10691



Exposed Pipeline. Green section corresponds to the piece of pipeline replaced. Some moisture at the bottom and on the walls. May be condensate or water. Distinctive hydrocarbon odor.

Lower part of the excavation: Fractured sandstone; overlain by weathered, crumbling rock. Sediment/soil at the top.

Inspection Photos
Location Name: Divide Rd WTF Pipeline Release
Spill/Release Point ID #453066
REM #10691



Looking east. Pipeline corridor and excavation at POR.



Looking northeast. A27 road at the bottom of the valley.

Inspection Photos

Location Name: Divide Rd WTF Pipeline Release

Spill/Release Point ID #453066

REM #10691



Walking northwest from the POR there is a depression, a cut. First monitoring wells were installed down at the bottom.



Looking west. Road to A27 CDP at the distance.



Inspection Photos

Location Name: Divide Rd WTF Pipeline Release

Spill/Release Point ID #453066

REM #10691



A27 road seen from above (from the ridge).



One of the monitoring wells installed by Caerus. Orange sticks differentiate Caerus wells from Encana wells (have yellow sticks).



Inspection Photos
Location Name: Divide Rd WTF Pipeline Release
Spill/Release Point ID #453066
REM #10691



12/04/2017. Pressure test conducted on 10" condensate pipeline.