

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/14/2017

Submitted Date:

12/06/2017

Document Number:

688500002

FIELD INSPECTION FORM

Loc ID 437161 Inspector Name: CANFIELD, CHRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Phil Hamlin	970-515-1161	phil.hamlin@anadarko.com	Mr. Hamlin was present during htis inspection.

General Comment:

[Environmental Inspection in response to Complaint 200443291.](#)

Environmental

Spills/Releases:

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: A paraffin plug caused a pressure buildup within a horizontal separator. As a result, a pressure relief valve opened releasing a mist of condensate and water. The volume of the release is believed to be less than one (1) barrel. Some of the mist landed on the separator and soil within the secondary containment surrounding it. A portion of the mist landed on soils off of the subject location. All soils that came in contact with the mist were scraped to a depth of six (6) inches. Approximately six (6) cubic yards of soil was transported to the Front Range Landfill for disposal. The scraped area was treated with an amendment designed to biodegrade petroleum hydrocarbons, covered with clean soil, and restored to previous contours. A total of seven (7) soil samples were collected and submitted for laboratory analysis to verify the cleanup.

Corrective Action: _____ Date: _____

Reportable: NO

GPS: Lat 40.005467

Long -104.925034

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688500003	Photo Log - Sack 2C-30HZ - Inspection 07-14-2017	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321467