



**Photo 1. View of the project area from the northeastern corner facing center.**



**Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Well pad size is reduced and interim reclamation areas are incorporated into surrounded cropland. Vegetation in disturbance areas should be monitored in comparison to reference vegetation.**





**Photo 3. View of the western portion of the project area from the northwestern corner facing southward.**







**Photo 4. View of wattles in the western portion of the project area. These appear to need maintenance, and do not appear to be sufficient length to prevent concentrated runoff from the well pad eroding adjacent crop soils.**





**Photo 5. View of wattle at the entrance to the well pad, needs maintenance.**





**Photo 6. View of wattles along the southern portion of the access road, appear to be functioning.**