

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401485380

Date Received:
12/13/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

-

SanJuanCOGCC@bp.com

Beebe, Sabre

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602244

Inspection Date: 11/09/2017

FIR Submit Date: 11/27/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326582

Location Name: DULIN, ROBERT GAS UNIT Number: 25NESW County: LA PLATA
A-N35N7W

Qtrqr: NESW Sec: 25 Twp: 35N Range: 7W Meridian: N

Latitude: 37.269304 Longitude: -107.589754

FACILITY - API Number: 05-067- -00 Facility ID: 258289

Facility Name: ROBERT DULIN A2 Number: _____

Qtrqr: NESW Sec: 25 Twp: 35N Range: 7W Meridian: N

Latitude: 37.269304 Longitude: -107.589754

CORRECTIVE ACTIONS:

1 CA# 112066

Corrective Action: Install stormwater controls to stabilize erosion within the project area.

Date: 12/29/2017

Response: CA COMPLETED

Date of Completion: 12/11/2017

Operator
Comment:

Erosion around the valve can has been back filled to prevent future erosion. Diversion ditches have been re-established and installed to flow storm water towards newly installed rock run downs with check dams to prevent future rilling by storm water. Fence was found by operator to be damaged by a fallen tree repairs were made to the fencing around location as well. See attached photos of all work completed.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Erosion around the valve can has been back filled to prevent future erosion. Diversion ditches have been re-established and installed to flow storm water towards newly installed rock run downs with check dams to prevent future rilling by storm water. Fence was found by operator to be damaged by a fallen tree repairs were made to the fencing around location as well. See attached photos of all work completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Construction Specialist

Date: 12/13/2017 3:32:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401485388	Photos of work completed

Total Attach: 1 Files