



Photo 1. View of area in the northeastern portion of the project area where it appears Russian knapweeds have been treated.



Photo 2. View of berm in the western portion of the project area.





Photo 3. View of cobble run-down in the western portion of the project area.