

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2017

Submitted Date:

12/15/2017

Document Number:

680705165**FIELD INSPECTION FORM**
 Loc ID 331189 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|--------------------------|---------|
| , | | cogccinspection@pdce.com | |
| Leonard, Mike | | mike.leonard@state.co.us | |
| Precup, Jim | | james.precup@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 259244 | WELL | PR | 04/30/2001 | OW | 123-20281 | OLSON 24-29 | PR |

General Comment:

Location

| | | | |
|--------------------|---|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access road damage noted in prior inspection document #680705087 has been repaired. | | |
| Corrective Action | L | Date: | |

Overall Good: ☐

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|----------------------|----------------------------|
| Emergency Contact Number: | | |
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: <input type="text"/> |

| | | | |
|---------------------------|------------------|-------|--|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused meter run | | |
| Corrective Action: | | Date: | |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Livestock fencing | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Livestock fencing | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-------------------|-------|--|
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | Automation array, solar array and ECD scrubber | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|--------------------|---|----------|----------------|---------|-----------------------|--|
| PRODUCED WATER | 1 | 100 BBLS | PBV FIBERGLASS | | 40.277200,-104.914020 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | | |
|------------------|----------|--|--|
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| | | | | | | | | | | |
|--------------------|----------|---|---------------------|-----------|---------------------|---------|-----------------------|--|-------|--|
| Type | Capacity | | Permeability (Wall) | | Permeability (Base) | | Maintenance | | | |
| Earth | Adequate | | Walls Sufficent | | Base Sufficient | | Adequate | | | |
| Comment: | | | | | | | | | | |
| Corrective Action: | | | | | | | | | Date: | |
| Contents | | # | Capacity | Type | | Tank ID | SE GPS | | | |
| CRUDE OIL | | 2 | 400 BBLS | STEEL AST | | | 40.277200,-104.914120 | | | |
| Comment: | | | | | | | | | | |

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|--|
| Corrective Action: | | | | | Date: | |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|---|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 259244 | Type: | WELL | API Number: | 123-20281 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| BradenHead | | | | | | | | | |
| Comment: | | Bradenhead valve is exposed at surface. | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

| Environmental | |
|------------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): YES | |
| Comment: | |
| Pilot: ON | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 680705166 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4327642 |