

Inspection Photos
Location Name: Semler #1
API: 05-067-07909



Semler #1 well head and pump jack.



Stained soil and excavation around well head.

Inspection Photos
Location Name: Semler #1
API: 05-067-07909



Stained soil noted on inspection document #674901962 has been removed.



Stained soil and open excavation at well head.

Inspection Photos
Location Name: Semler #1
API: 05-067-07909



Alternate view of excavation near well head.



Secondary containment berm for tank battery has been repaired.