

Inspection Photos
Location Name: Herrera MV #1
API: 05-067-05410



Open topped PW vessel.



Secondary containment berm has been repaired.

Inspection Photos
Location Name: Herrera MV #1
API: 05-067-05410



Secondary containment berm maintained to provide adequate capacity.



Herrera MV #1 well head and dehy unit.