



Photo 1. View of straw and area with documented erosion, appears to be functioning, but controls may not be sufficient. No clear whether the area was seeded.



Photo 2. View of area where erosional channel has been filled and straw applied. Not clear whether it's been seeded.



Photo 3. View of another area where erosional channel has been filled and straw applied. Not clear whether it's been seeded.