

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 1: Wellhead sign. Previous inspection.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 2: Wellhead sign.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 3: Separation in E fill slope. Previous inspection.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 4: Repair made to the separation in E fill slope.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 5: Closer view of separation. Previous inspection.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 6: Closer view of repair made to the separation.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 7: Rock in the repair to the erosion channel on fill slope.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 8: Additional view of repair in the fill slope..

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 9: Rock on rill slope.

- Southern Ute 33 – 10; 15 - 3
- 05-067-08833



Photo 10: Location overview.