



Photo 1. View of area recently reclaimed. From the southwester edge facing eastward. Showing erosion control blanket and fencing.



Photo 2. View of reclaimed area from the southern portion facing northward toward riser.



Photo 3. View of reclaimed area from the southern portion facing northwestward.



Photo 4. View of area of exposed soils from the access road facing upslope along the pipeline alignment toward the riser at the top of the hill. This area should be seeded and carefully monitored until stabilized.

