

Location

Lease Road:

Type	Main				
comment:					
Corrective ActionL				Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	

Emergency Contact Number:

Comment:	ok				
Corrective Action:				Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

					corrective date
Type: Pump Jack	# 1				
Comment:	not in use changed over to plunger lift				
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:	intermitter controller on wellhead				
Corrective Action:				Date:	

Venting:

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:

Type	Ignitor/Combustor				
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 203510 Type: WELL API Number: 001-09070 Status: SI Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

BradenHead

Comment: ok

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
document # 685503995, dated 9/26/17 unused equipment picked up soild dirt around wellhead and motor mounts cleaned up	montoyaj	12/19/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677400244	wellhead and ajax motor	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4330818