

Inspection Photos

12/18/2017

Operator: PETRO-CANADA RESOURCES (USA)
INC - 72085

Location ID: 376781

Inspection Doc. Number: 682502978
Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 376781



Photo 1: Photo taken from the west end of the well pad location, facing north. Photo shows well pad appears to have been recontoured/regraded, reseeded and crimped with straw for stabilization.



Photo 2: Photo taken from the west end of the well pad location, facing east. Photo shows well pad appears to have been recontoured/regraded, reseeded and crimped with straw for stabilization.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 376781



Photo 3: Photo taken from the west end of the well pad location, facing southeast. Photo shows well pad appears to have been recontoured/regraded, reseeded and crimped with straw for stabilization.



Photo 4: Photo taken from the west end of the well pad location, facing south. Photo shows well pad appears to have been recontoured/regraded, reseeded and crimped with straw for stabilization.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 376781



Photo 5: Photo taken southwest corner of the well location, facing south. Photo shows well pad appears to have been recontoured/regraded, seeded and stabilized w/ matting.



Photo 6: Photo taken southwest corner of the well location, facing east. Photo shows well pad appears to have been recontoured/regraded, seeded and stabilized w/ matting.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 376781



Photo 7: Photo taken from well location, facing north. Photo shows gravel has been removed from well location and area appears to have been reseeded and crimped with straw for stabilization.



Photo 8: Photo taken from well location, facing southwest. Photo shows gravel has been removed from well location and area appears to have been reseeded and crimped with straw for stabilization.



Photo 9: Photo taken from within the fenced remediation area, facing west. Previous inspections identified areas within the remediation area that remain bare and unvegetated, or predominantly undesirable weedy plant species and required additional reclamation to be performed. Photo shows bare and exposed areas. Unable to find evidence that additional reclamation activities have been conducted on these areas per the corrective action.



Photo 10: Photo taken from within the fenced remediation area, facing south. Previous inspections identified areas within the remediation area that remain bare and unvegetated, or predominantly undesirable weedy plant species and required additional reclamation to be performed. Photo shows areas where vegetation is predominantly undesirable weedy plant species. Unable to find evidence that additional reclamation activities have been conducted on these areas per the corrective action.



Photo 11: Photo taken from the access road, facing east. Photo shows area of access road that appears to have been regraded, seeded and crimped with straw for stabilization.