



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southeastward. Little soil is present in interim reclamation areas due to dense rocks. Revegetation is progressing in areas with soil.





Photo 4. View of the southern portion of the project area from the southeastern corner facing westward.