

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2017

Submitted Date:

12/21/2017

Document Number:

689400769**FIELD INSPECTION FORM**Loc ID 324471 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Inspections, All		inspection@sginterests.com	All Inspections
Arthur, Denise		denise.arthur@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275738	WELL	SI	07/01/2015	GW	051-06059	FEDERAL 11-90-35#1	TA

**General Comment:**

This is a follow up inspection to FIR Doc#689400574. Any corrective actions not addressed from previous inspections are still applicable.

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Capacity had not been added to tanks at the time of inspection. Original corrective action and date still apply.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	12/02/2017
Type	TANK LABELS/PLACARDS		
Comment:	New NFPA labels have been ordered, and unused tanks without labels have been removed. Corrective actions from previous inspection has been met.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	(866) 261-9766	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Multiple tanks and unused pipe manifold noted on Inspection Doc#680602116 have all been removed. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Locaton has been graded and no visible sign of staining at the time of inspection. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	0		STEEL AST		,
Comment:	Tanks have been removed. Corrective action from previous inspection has been met.				
Corrective Action:		Date:			

**Paint**

Condition	
Other (Content)	
Other (Capacity)	

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	400 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 275738 Type: WELL API Number: 051-06059 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Well last produced for 19 days in June 2015. MIT on 7/24/17. Form 4 Doc#401473868 in process. Corrective action from previous inspection has been met.Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400770	Federal 11-90-35#1 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4332608">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4332608</a>