

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2017

Submitted Date:

12/21/2017

Document Number:

689800680

**FIELD INSPECTION FORM**

Loc ID 451938 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10598  
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC  
Address: 123 ROBERT S KERR AVE  
City: OKLAHOMA CITY State: OK Zip: 73102

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451939	WELL	XX	08/30/2017		057-06602	Beaver Creek 0881 1-3H34	WK

**General Comment:**

[Routine FIU inspection, frack witness.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 451939 Type: WELL API Number: 057-06602 Status: XX Insp. Status: WK

**Well Stimulation**

Stimulation Company: Haliburton Stimulation Type: HYDRAULIC FRAC  
Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: 7426 PSI Tubing: \_\_\_\_\_  
Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) 3746  
Bradenhead Psi: \_\_\_\_\_ Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: Inspector on location to witness perms on stage 28 and frack on stage 27.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Completion**

Operation: \_\_\_\_\_  
Date Flowback: \_\_\_\_\_  
Contractor: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT