



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southeastward. Revegetation is progressing with grasses and shrubs such as crested wheatgrass (*Agropyron cristatum*), blue grama (*Bouteloua gracilis*), western wheatgrass (*Pascopyrum smithii*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 4. View of area in the northwestern portion of the project area where it appears stormwater causing erosion from run-on and concentrated stormwater flows off of the project area. This should be monitored and stormwater controls applied if it worsens.



Photo 5. View of Scotch thistles (*Cirsium arvense*) within the eastern portion of the project area.



Photo 6. View of erosion occurring along the access road where stormwater is flowing off of the road and eroding roadsides.



Photo 7. View of another area along the roadside where stormwater flows off of the roadsides and is causing erosion.



Photo 8. View of another area where erosion is occurring along the access road.