



**Photo 1:** Photo taken from the west end of the location facing east. Previous inspections documented that location had not achieved a uniform desirable perennial vegetative cover of 80% and required operator to perform reclamation. Photo shows areas of the location where additional reclamation was required. Though partially snow-covered, unable to find evidence that additional reclamation activities have been conducted.



**Photo 2:** Photo taken from the bare areas seen in photo 1. Photo shows soil; unable to find evidence that additional reclamation activities have been conducted per the corrective action.