

**Inspection Photos**  
**Location Name: State-Hoppe 16-2**  
**API #: 05-123-12520**  
**Location ID: 323075**



**Wellhead looking east**



**Stained soil under master valve. Appears to be leaking/have leaked from wellhead packing**

## Inspection Photos

Location Name: State-Hoppe 16-2

API #: 05-123-12520

Location ID: 323075



Battery looking north. Crude oil tank is north approx. 190 yards from separator



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources