

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/22/2017

Submitted Date:

12/22/2017

Document Number:

680705214

**FIELD INSPECTION FORM**

Loc ID 331801 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266097	WELL	SI	02/01/2016	GW	123-21323	WYSCAVER 13-5	PA

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 266097 Type: WELL API Number: 123-21323 Status: SI Insp. Status: PA

**BradenHead**

Comment: Bradenhead valve is exposed at surface.

Corrective Action:

Date:

**Workover**

Comment: POOH with tbg, MIRU Casedhole Solutions wireline, RIH with junk basket/guage ring combination to 7100' KB, POOH with tools, RIH with 4 1/2" 10K CIBP #1 and set @ 7050' KB, POOH with setting tool, RIH with dumpbailer and spot 2 sxs of cement on top of CIBP, POOH with dumpbailer, RIH with 4 1/2" 10K CIBP #2 and set @ 6317' KB, POOH with setting tool, RIH with dumpbailer and spot 2 sxs of cement on top of CIBP, POOH with dumpbailer, pressure test csg to 1600# with no leak off, RIH with jet cutter and cut csg @ 1500' KB, POOH with spent cutter, RDMO wireline, SIW, SDFN.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680705215	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4334441">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4334441</a>