

Inspection Photos
Location Name: Linhart 3-33
API #: 05-123-13438
Location ID: 323735



Wellhead looking east.



1" steel riser has been cut/capped below surface

Inspection Photos
Location Name: Linhart 3-33
API #: 05-123-13438
Location ID: 323735



Wellhead looking east from previous inspection



1" steel riser at wellhead from previous inspection