

Photo#1:
Overview of Location from Entry to SE.



October 12, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Dolphin Energy Loc#335691

Photo#2:
Overview of Location to North.



October 12, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Dolphin Energy Loc#335691

Photo#3:
Close up View of Vegetation to South.



October 12, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Dolphin Energy Loc#335691

Photo#4:

View of Swale area where Vegetation has Failed & mulch has washed.



October 12, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Dolphin Energy Loc#335691

Photo#5:

Knap weed has established in some areas of Location.



October 12, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Dolphin Energy Loc#335691