

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 326968



Photo 1: Photo taken from the northeast end of the location, facing south. Previous inspections required operator to perform additional reclamation on the location. Photo shows location appears to have been recontoured/regraded, seeded and crimped with straw for stabilization per the corrective action.



Photo 2: Photo taken from the northeast end of the location, facing south. See comments under photo 1.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 326968



Photo 3: Photo taken from the northeast end of the location, facing west. See comments under photo 1.



Photo 4: Photo taken from the location. Photo shows pipe riser equipment with Noble sign remaining on the location.



Photo 5: Photo of pipe riser from photo 4.



Photo 6: Photo taken from the location, facing east. Photo shows two (2) pipe risers remaining on the location. Riser seen in cage to the left is pipe seen in photo 4 and 5. Equipment to the right possibly belongs to DCP as a DCP flag was observed at its base.



Photo 7: Photo of equipment seen in photo 6 from the east, facing west.



Photo 8: Photo of DCP flag observed next to riser equipment. This flag can be seen in the left side of photo 7.