


Location Name: TEP API 045-06918

12/18/2017



Failed Frac line elbow

PW line being re-capped in valve can

TEP 045-06918

Inspection 12/18/17



Stormwater pond looking north towards spill point



Stormwater pond post-spill excavation looking east

