



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	SATISFACTORY		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:			Date:
Type	BATTERY		
Comment:	SATISFACTORY		
Corrective Action:			Date:

**Emergency Contact Number:**

Comment: SATISFACTORY

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	Architectural steel		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Barbed wire topped chain link		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Architectural steel		
Corrective Action:			Date:

**Equipment:**

Type:	#		corrective date
Comment:	Refer to inspection # 681902445 for information concerning shared battery and equipment.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS

Comment:	Refer to inspection # 681902445 for information concerning shared battery and equipment.	
Corrective Action:		Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 268773 Type: WELL API Number: 123-21594 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Bradenhead is plumed to surface.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681902449	well	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4336131">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4336131</a>