

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2017

Submitted Date:

12/27/2017

Document Number:

681902456

FIELD INSPECTION FORM

Loc ID 318928 Inspector Name: HELGELAND, GARY On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 39560
Name of Operator: TOP OPERATING COMPANY FDDB MURRAY J
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKWOOD State: CO Zip: 80235

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
HERRING, PAUL		paul.herring@topoperating.com	
Axelson, John		john.axelson@state.co.us	
HERRING, MURRAY J		murray.herring@topoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242499	WELL	PR	12/03/2012	GW	123-10290	SERAFINI GAS UNIT 1	PR

General Comment:

This is considered a "high risk" location and was inspected on that basis. This inspection only indicates conditions as they exist at the time of inspection. It was unclear during the inspection what, if anything, had been done to implement the Supplemental Work Plan. At Time of inspection production equipment was operational and hydrocarbons were being produced. The well on location was S/I.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	SATISFACTORY		
Corrective Action:			Date:
Type	BATTERY		
Comment:	SATISFACTORY		
Corrective Action:			Date:

Emergency Contact Number:

Comment: SATISFACTORY

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: Can not determine. Location snow covered.

Multiple Spills and Releases?

Equipment:

Type				corrective date
Emission Control Device	# 2			
Comment:				
Corrective Action:				Date:
Bird Protectors	# 5			
Comment:				
Corrective Action:				Date:
Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:				Date:
Pig Station	# 3			
Comment:				
Corrective Action:				Date:
Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 242499 Type: WELL API Number: 123-10290 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Comment:

Corrective Action: Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

COGCC Comments

Comment	User	Date
Issues may remain. Refer to inspection # 688500018 and # 688500016. A follow up inspection is required.	helgelag	12/27/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681902457	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4336135