

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2017

Submitted Date:

12/20/2017

Document Number:

688600160**FIELD INSPECTION FORM**

Loc ID 428669 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 1Name of Operator: UNKNOWN

Address: _____

City: _____ State: _____ Zip: _____

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425793	WELL	TA	10/12/2011	LO	077-40017	Lloyd and Lowell 1	TA

General Comment:

Orphan well plugging project. Contractor is RACS.

Inspected FacilitiesFacility ID: 425793 Type: WELL API Number: 077-40017 Status: TA Insp. Status: TA**Workover**

Comment: Removed shallow fish with hydrovac. Ran tape to 130'. Ran downhole camera to fish/bridge at 165'.
Completed rigging up to drill out fish/bridge.

Corrective Action: Plug and abandon.

Date: 12/30/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401493943	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4333287