



**Photo 1. View of the project area from the northwestern entrance facing center. Truck, trailer and pipes should be removed.**





**Photo 2. View of the western portion of the project area from the northwestern corner facing southward.**





**Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward. Trailers and vehicles in right portion of photo are parked on cement pad and appear to be outside of the project area.**





**Photo 4. View of the eastern portion of the project area from the southeastern edge facing northward. Revegetation is largely comprised of smooth brome (*Bromus inermis*) and dropseed (*Sporobolus* sp.).**





**Photo 4. View of musk thistles (*Carduus nutans*) in the western portion of the project area.**