



**Photo 1. View of the project area from the southwestern corner facing center.**



**Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward.**



**Photo 3. View of the western portion of the project area from the southwestern corner facing northward.**



**Photo 4. View of musk thistles (*Carduus nutans*) within the interim reclamation area. Project area is infested with musk thistles.**



**Photo 5. View of area in the southeastern portion of the project area that does not appear to be in use and should be revegetated.**



**Photo 6. View of jointed goatgrass (*Aegilops cylindrica*) in the western portion of the project area.**