



Photo 1. View of the project area from the northeastern corner facing center. It appears that cattle are being fed on the well pad.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 3. View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation is progressing, but significantly grazed. Snakeweed (*Gutierrezia sarothrae*) and crested wheatgrass (*Agropyron cristatum*) are observable.



Photo 4. View of cement debris within the northern portion of the project area.



Photo 5. View of wood debris in the northeastern portion of the project area.



Photo 6. View of wood and cement debris along the northern edge of the well pad.