



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward.





Photo 3. View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*), and dropseed (*Sporobolus* sp.).



Photo 4. View of pipes stored in the southeastern project area.



Photo 5. View of area along the cut-slope where vehicles are driving and have damaged vegetation. This area needs to be stabilized.