

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2017

Submitted Date:

12/27/2017

Document Number:

681700969**FIELD INSPECTION FORM**Loc ID 320663 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Condill, J. B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	All Inspections
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204346	WELL	PR	09/08/1997	OW	005-06431	PAR-STATE 28-1	EI

General Comment:[COGCC Environmental Inspection of wellhead, pump jack, and tank battery. Follow-up to Field Inspection Report \(FIR\) #680700864.](#)

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Oily rag on fence at tank battery. See photos.		
Corrective Action:	Comply with Rule 603.f. (oily rag)	Date:	01/27/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed wire fence in need of repair on north side. See photos.		
Corrective Action:	Repair fence as part of routine maintenance.	Date:	03/27/2018
Type	PUMP JACK		
Comment:	Barbed wire fence.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire fence.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Day tank at pump jack has adequate secondary containment.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Operator has removed oily waste beneath pump jack in response to previous FIR.		
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:	Operator has removed oily waste at wellhead in response to previous FIR.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	Operator had removed oil-stained soil from north side of AST, but it has started to accumulate again. See photos. Continued inspection and maintenance required.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		
Comment:	Earthen berms shared with crude oil ASTs. Berms are shallow due to erosion. See photos.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		
Comment:	Earthen berms shared with produced water AST. Berms are shallow due to erosion. See photos.			
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 204346 Type: WELL API Number: 005-06431 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401495879	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335301
681700978	Field photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335296