

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/26/2017

Submitted Date:

12/26/2017

Document Number:

684904793

FIELD INSPECTION FORM

Loc ID 332020 Inspector Name: Pesicka, Conor On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 269735 | WELL | PR | 03/28/2012 | OW | 123-21723 | KREPS TRUST 34-6 | PR |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Wellhead operator from proximity to battery | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|--|
| Comment: | <input type="text"/> | Date: | |
| Corrective Action: | <input type="text"/> | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-------------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | wire | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | agricultural | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | agricultural | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Type: Compressor | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |

| | | | |
|-------------------------------|--|-------|------------------|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Audible hiss and frost build up on valve in meter run | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (24 hr CA due to leak) | | Date: 12/27/2017 |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER | 1 | 100 BBLS | PBV FIBERGLASS | | 40.508480,-104.589420 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: | Shared with crude oil | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | | 40.508480,-104.589420 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

| Berms | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| Venting: | | | | | |
|--------------------|----|--|--|-------|--|
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| Flaring: | | | | | |
|--------------------|--|--|--|-------|--|
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Inspected Facilities

Facility ID: 269735 Type: WELL API Number: 123-21723 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI.

Corrective Action: Date:

BradenHead

Comment: Bradenhead plumbed to surface.

Corrective Action: Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: OFF Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| Contacted operator at 0915hr on 12/26/17 | pesickac | 12/26/2017 |
| Met with pumper on site @0930hr on 12/26/17 | | |
| DCP contacted by operator. | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------|---|
| 401495653 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335014 |
| 684904794 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335011 |
| 684904795 | Leak at DCP needle valve | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4335012 |