

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2017

Submitted Date:

01/02/2018

Document Number:

689400794

**FIELD INSPECTION FORM**

Loc ID 334625 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Caerus Oil,		COGCC.inspections@caerusoilandgas.com	<a href="#">All Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211561	WELL	PR	08/02/2003	GW	045-07321	BENTLEY 11-23	PR
268858	WELL	PR	11/07/2003	GW	045-09305	BENTLEY 11-13D	PR
269088	WELL	PR	08/13/2003	GW	045-09316	BENTLEY 11-14D	PR

**General Comment:**

[This is a follow up inspection to FIR Doc#689400394. Any corrective actions not addressed from previous inspections are still applicable.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition Adequate

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: <u>211561</u>	Type: <u>WELL</u>	API Number: <u>045-07321</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<a href="#">Plunger</a>		
Corrective Action:		Date:	
Facility ID: <u>268858</u>	Type: <u>WELL</u>	API Number: <u>045-09305</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<a href="#">Cement bond log submitted Doc#2597367. Form 17 attached to inspection.</a>		
Corrective Action:		Date:	
Facility ID: <u>269088</u>	Type: <u>WELL</u>	API Number: <u>045-09316</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<a href="#">Plunger</a>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Work has been done around separators but unable to do complet stormwater inspection due to snow cover. Will re-evaluate when conditions allow.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689400795	Bentley Follow up photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4339264">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4339264</a>
689400806	Form 17	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4339265">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4339265</a>