

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 1: Wellhead sign. Previous inspection document number 685303916.

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 2: New wellhead sign. Current inspection.

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 3: Valve, nipple, and production related materials at wellhead. Previous inspection document number 685303916.

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 4: Removed production related materials at wellhead. Current inspection.

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 5: Polished rod at wellhead. Previous inspection document number 685303916.

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 6: Removed polished rod at wellhead. Current inspection.

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 7: Plastic debris along E access road. Previous inspection document number 685304025.

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 8: Plastic debris along E access road 2. Current inspection.