



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 3. View of the western portion of the project area from the northwestern corner facing southward. Vegetation is progressing within the interim reclamation areas with grasses such as smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and weeds such as cheatgrass (*Bromus tectorum*) and kochia (*Kochia scoparia*).





Photo 4. View of area where concentrated stormwater flows off of the southwestern corner of the well pad and tunnels through the interim reclamation area.



Photo 5. Another view of area in southwestern portion of the project area where erosional channels are tunneling through the interim reclamation area. This area needs stabilization.