



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the southern portion of the project area from the northeastern corner facing westward. Revegetation is grazed and not in identifiable form.



Photo 4. View of stormwater controls in the southern portion of the project area, appear to be functioning.



Photo 5. View of the western portion of the project area from the southwestern corner facing northward. Scotch thistles (*Onopordum acanthium*) and musk thistles (*Carduus nutans*) are growing here.





Photo 5. View of signs that appear to have been replaced since last inspection.