

Inspection Photos
Location Name: Federal 1-2 #2
API: 05-067-09066



95 bbl. PBV without secondary containment.



PBV and valve can with location in the background.

Inspection Photos
Location Name: Federal 1-2 #2
API: 05-067-09066



Pipeline risers north of well pad.



Valves are locked out on risers.

Inspection Photos
Location Name: Federal 1-2 #2
API: 05-067-09066



Equipment on location is locked out and flow lines are painted.



Two risers painted orange with bull plugs.

Inspection Photos
Location Name: Federal 1-2 #2
API: 05-067-09066



Area where release may have occurred.



Area down gradient of previous picture.

Inspection Photos
Location Name: Federal 1-2 #2
API: 05-067-09066



Disturbed area where release may have occurred.



Erosional channel along southern edge of location.