

**Inspection Photos**  
**Location Name: Black 21-22 #4**  
**API: 05-067-09600**



**Stained soil and gravel near muffler exhaust for #2 prime mover.**



**Stained soil beneath prime mover for #2 pump jack.**

**Inspection Photos**  
**Location Name: Black 21-22 #4**  
**API: 05-067-09600**



**Stained soil around #2 well head. Absorbent rags tied to well head are saturated.**



**Stained soil and gravel near muffler exhaust for #4 prime mover.**

Inspection Photos  
Location Name: Black 21-22 #4  
API: 05-067-09600



BP representative on site installing a float controlled trap.



Float controlled trap being installed on well #4.

**Inspection Photos**  
**Location Name: Black 21-22 #4**  
**API: 05-067-09600**



**Dirt pile in SW corner of location.**



**Black 21-22 #2 and #4 location photo.**