

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



Lark 33-5 #21-4 well head.



Mark left from horizontal tank skid.

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



Proximity of release in relation to well head.



Produced water line leak observed in separator shack.

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



Produced water leaking from separator shack.



Petrox representative repairing produced water line in separator shack.

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



Location of sample collection point, 37.08489/-107.40588.




5 – 4 oz. jars and two ziploc bags of impacted material collected by Petrox representative.

Inspection Photos
Location Name: Lark 33-5 #21-4
API: 05-007-06323



Petrox representative temporarily correcting contact information on well sign.



Well sign contact information temporarily corrected.