



**Photo 1. View of the project area from the northwestern corner facing center.**



**Photo 2. View of the project area from the northwestern edge facing southward.**



**Photo 3. View of equipment and soil/rock stockpiles where the former pit appears to be in the process of being filled. Interim reclamation has not been conducted.**



**Photo 4. View of area where old pit is being filled in the northwestern project area.**



**Photo 5. Another view of pit area in the northwestern project area that appears to be in the process of being filled.**