

Photo#1:
View North over Location Center



Photo#2:
View South over Location Center



December 20, 2017


Photo#3:

View East over Location Center



Photo#4:

View West over Location Center



December 20, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Standard Shale API#045-06914

Photo#5:

Access Road into Location has Not been Reclaimed.



December 20, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Standard Shale API#045-06914

Photo#6:

Access Road into Location has Not been Reclaimed.


Photo#7:



December 20, 2017

Photo#8:

From Aerial Photos it appears Road was built to Access Location.



December 20, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Standard Shale API#045-06914

Photo#9:

Old sign is only Debris on Location & will need to be removed before Final Reclamation is Passed.



December 20, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Encana PA Standard Shale API#045-06914