

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2018

Submitted Date:

01/08/2018

Document Number:

690100299

FIELD INSPECTION FORM

Loc ID 425062 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		NBL_DJBU_Inspections@NBLENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425163	WELL	PR	12/30/2011	OW	123-34287	NORTHRUP C 08-73HN	EG

General Comment:

Engineering Integrity Inspection performed on January 4th, 2018 in response to initial form 19 spill report Doc #401493675 received by COGCC on 12/21/2017 that outlines: During maintenance operations at the Northrup C8-73 location, an unintentional release was discovered from the produced water line running from the separator to the tanks. The location is shut in and soil impacts are being excavated. Details of observations made during this field inspection are available in the flowline section of this report. Photos uploaded can be accessed via link(s) at end of this report.

Inspected Facilities

Facility ID: 425163 Type: WELL API Number: 123-34287 Status: PR Insp. Status: EG

Flowline

#1	Type: Dump Line	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Dump Line Size: 2" Material:
 Variance: Age: Contents: Produced Water

Integrity Summary

Failures: Spills: Yes Repairs Made: Yes
 Coatings: H2S: No Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Noble Energy or contract personnel were not on site at the time of this field inspection. Repairs appear to have been completed on the produced water dump flowline. Cleanup and remediation work also appears to be completed. The facility berms have been rebuilt and area regraded. *Note: Document and retain records of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of all flowline repairs completed (*on supplemental form 19); perform flowline pressure testing (dump lines) to verify integrity of repairs completed (retain chart & data) prior to returning dumpline(s) to service.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690100301	Battery and Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344000
690100303	Reconstructed berm and PW Vaults	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344001
690100304	View west toward separators	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344002