

Inspector Name:

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/02/2018

Submitted Date:

01/03/2018

Document Number:

681902458

FIELD INSPECTION FORM

Loc ID 336421 Inspector Name: _____ On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290

Name of Operator: K P KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
2 Number of Corrective Actions
☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
LARA-MESA, SUSANA	303-825-4822	cogcc@kpk.com	VP OF ENGINEER

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241485	WELL	SI	10/01/2017	OW	123-09274	EARL ANDERSON 2	PR

General Comment:

Inspector Name:

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	SATISFACTORY			
Corrective Action:				Date:
Type	BATTERY			
Comment:	All wells flowing to this battery are not identified on Battery Sign.			
Corrective Action:	Install sign to comply with Rule 210.b.			Date: 02/02/2018
Type	WELLHEAD			
Comment:	SATISFACTORY			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	SATISFACTORY			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Rod fence.			
Corrective Action:				Date:
Equipment:				
Type: Horizontal Heated Separator			# 1	corrective date
Comment:			SATISFACTORY	
Corrective Action:			Date:	
Type: Gas Meter Run			# 1	
Comment:			SATISFACTORY	
Corrective Action:			Date:	
Type: Plunger Lift			# 1	
Comment:			SATISFACTORY	
Corrective Action:			Date:	
Type: Bird Protectors			# 1	
Comment:			SATISFACTORY	
Corrective Action:			Date:	

Inspector Name:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		40.122602,-104.992865	
Comment: Longitude:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.122397,-104.992063	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspector Name:

Inspected Facilities

Facility ID: 241485 Type: WELL API Number: 123-09274 Status: SI Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: BRADENHEAD IS NOT PLUMED TO SURFACE FOR PRESSURE MONITORING.

Corrective Action: PLUMB BRADENHEAD TO SURFACE.

Date: 02/02/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401501895	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4340074
681902459	Well and Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4340068