

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/10/2018

Submitted Date:

01/10/2018

Document Number:

689300620

**FIELD INSPECTION FORM**

Loc ID 306172 Inspector Name: O'Donnell, Shaun On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10110  
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
Address: 1801 BROADWAY #500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspections@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286097	WELL	TA	01/01/2017	GW	123-24121	GREAT WESTERN 27-42	SI

**General Comment:**

Location					
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	Adequate				Date:
Corrective Action:					Date: _____
<b>Good Housekeeping:</b>					
Type	OTHER				
Comment:	Stained soil around wellhead. See attached photos				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.				Date: 02/10/2018
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	WELLHEAD				
Comment:	Chain link				
Corrective Action:					Date:
<b>Equipment:</b>					
					corrective date
Type: Plunger Lift	#	# 1			
Comment:					
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

**Flaring:**

Type				
Comment:				
Corrective Action:			Date:	

**Inspected Facilities**

Facility ID: 286097 Type: WELL API Number: 123-24121 Status: TA Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Lubricator is not tied into flowline. Casing is still tied into flowline, capable of producing from well

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead valve is exposed at surface

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689300621	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4346536">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4346536</a>