

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



**Photo 2. No wellhead sign. Risers at wellhead.
1/3/2018**



**Photo 3. No wellhead sign. Risers at wellhead.
6/6/2017**

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 4. Risers at entrance.
1/3/2018



Photo 5. Risers at entrance.
6/6/2017

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 6. Free fluid at tank base.
1/3/2018



Photo 7. Free fluid at tank base.
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 8. Free fluid and stained soil at tank base.
1/3/2018



Photo 9. Stained soil at tank base.
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 10. Hole in tank. Stained soil and free fluid at base.
1/3/2018



Photo 11. Hole in tank. Stained soil and free fluid at base.
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 12. Unmarked riser.
1/3/2018



Photo 13. Unmarked riser.
6/6/2017

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 14. Stained soil and debris.
1/3/2018



Photo 15. Stained soil and debris.
6/6/2017

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 16. Stained soil at tank loadouts.
1/3/2018



Photo 17. Stained soil at tank loadouts.
6/6/2017

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 18. Stained soil at tank loadout.
1/3/2018



Photo 19. Stained soil at tank loadout.
6/6/2017

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 20. Pit. Unmarked riser in right foreground.
1/3/2018



Photo 21. Pit. Unmarked riser.
6/6/2017

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



**Photo 22. Netting sagging into pit. Oil present.
Less than 2 feet of freeboard.
1/3/2018**



**Photo 23. Netting sagging into pit. Oil present. Less than
2 feet of freeboard.
6/6/2017**

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 24. Stained soil on eastern side of pit.
1/3/2018



Photo 25. Incomplete tank labels.
1/3/2018

Inspection Photos
Location Name: Iles Investment CO 1-23
API: 05-081-05136



Photo 26. No tank labels. No berms.
1/3/2018



Photo 27. No tank labels. No berms.
6/6/2017